DEPARTMENT OF TRANSPORT

NOTICE 495 OF 2017

AIR SERVICE LICENSING ACT, 1990 (ACT NO.115 OF 1990) APPLICATION FOR THE GRANT OR AMENDMENT OF DOMESTIC AIR SERVICE LICENCE

Pursuant to the provisions of section 15 (1) (b) of Act No. 115 of 1990 and Regulation 8 of the Domestic Air Regulations, 1991, it is hereby notified for general information that the application detail of which appear in the appendix, will be considered by the Air Service Licensing Council. Representation in accordance with section 15 (3) of the Act No.115 of 1990 in support of, or in position, an application, should reach the Air Service Licensing Council. Private Box X 193, Pretoria, 0001, within 21 days of date of the publication thereof.

APPENDIX I

- (A) Full name and trade name of the applicant. (B) Full business or residential address of the applicant. (C) Class of licence applied for. (D) Type of air service to which application applies. (E) Category of aircraft to which application applies.
- (A) Dragoncam (Pty) Ltd. (B) 7 Buitensorg, Edgemead, Cape Town, 7441. (C) Class III. (D) Type G16 (Remotely Piloted Aircraft Systems). (E) Category H1.
- (A) Lekwa Consulting Engineers (Pty) Ltd; Lekwa Consulting Engineers (Pty) Ltd.
 (B) 118 Hennie Alberts Street, Braken Hurst, 1448. (C) Class III. (D) Type G16 (Remotely Piloted Aircraft Systems). (E) Category H1.

APPENDIX II

- (A) Full Name and trade name of the applicant. (B) Full business or residential address the applicant. (C) The Class and number of license in respect of which the amendment is sought (D) Type of air service and the amendment thereto which is being applied for (E) Category of aircraft and the amendment thereto which is being applied for. (F) Amendment reffered to in section 14(2) (b) to I.
- (A) Changing Tides 1126 CC; Suncatchers Hot Air Balloon Safaris. (B) Portion 18, Moriah Farm, Hoedspruit. (C) Class II; N691D. (D) N1. (E) Category A4. Changes to contact details, address and Management Plan: Wynand Uys replaces Philip Koornhof as the Chief Executive Officer & RP: Flight Operations, Duncan Robertson replaces Conrad van Wyk as the RP: Aircraft and Maritza de Kock replaces Philip Koornhof as the Air Service Safety Officer.
- (A) FC Hamman Films CC. (B) 128/2 Hilton Rd, Linbro Park, Santon. (C) Class III; G1277D. (D) Type G3, G4 & G16 (RPAS ops). (E) Category H1. Changes to the Management Plan: Odette van Jaarsveld replaces Paul Cumming as the Air Service Safety Officer & Quality Assurance Manager.
- (A) John Bassi Helicopters CC; Bassair Aviation. (B) Hangar #B6, New Tempe Airport, Bloemfontein. (C) Class II & III; N685D & G534D. (D) Type N1, N2, G3, G10 & G15. (E) Category H2. Changes to the Management Plan: Mr C. S. Bukes replaces Ms L. Bennetts as the Air Service Safety Officer.